

Oakland RFD

Oakland RFD

Doug_fir21A

Building Type Fire - RFPD	County Douglas	
Street 117 SE 3rd St		
City Oakland	State OR	Zip 97462
Latitude 43.42208	Longitude 123.29734	
Tracking Code RVS in 2006	Inspection Date 8/11/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	0	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Oakland RFD

Final RVS Score

Final Type	Final Score
URM	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1951	1951	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Over Exit		Cracks	
None		None	
None		None	
			
E	Field Verified Year Built	E	Primary Structural Type
			
E	Primary Structural Type		
			
SE	Vertical Irregularity Primary and reentrant corner	SW	Plan Irregularity Primary
			
W	Vertical Irregularity Primary		
			
W	Poor Condition		

