

Tiller RFPD

Doug_fir25A

Tiller RFPD

Building Type		County	
Fire - RFPD		Douglas	
Street			
27598 Tiller-Trail Hwy			
City	State	Zip	
Tiller	OR	97484	
Latitude		Longitude	
42.92855		122.95363	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Tiller RFPD

Final RVS Score

Final Type

Final Score

S3

2.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Elevation View



NE Elevation View



NW Elevation View

