

# Milo RFPD

Milo RFPD

Doug\_fir34A

Building Type		County	
Fire - RFPD		Douglas	
Street			
21484 Tiller Trail Hwy			
City	State	Zip	
Days Creek	OR	97429	
Latitude		Longitude	
42.93468		123.04019	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Milo RFPD

## Final RVS Score

Final Type

Final Score

S3

2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Elevation View



NE Elevation View



SE Elevation View