

Riddle FD

City of Riddle

Doug_fir35A

Building Type Fire - City	County Douglas	
Street 250 N Main St		
City Riddle	State OR	Zip 97469
Latitude 42.95015	Longitude 123.36647	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle FD

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE	Vertical Irregularity Primary	NE	Poor Condition
			
		W	Plan Irregularity Primary
			
SW	Vertical Irregularity Secondary	SW	Plan Irregularity Secondary

