

# Myrtle Creek FD

City of Myrtle Creek

Doug\_fir41A

Building Type		County	
Fire - City		Douglas	
Street			
601 NE Riverside Dr			
City	State	Zip	
Myrtle Creek	OR	97457	
Latitude		Longitude	
43.02299		123.28098	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Creek FD

## Final RVS Score

Final Type

Final Score

--	--

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1997	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions