

North Douglas County Fire & EMS

North Douglas County Fire & EMS

Doug_fir43A

Building Type	County	
Fire - RFPD	Douglas	
Street		
560 Scotts Valley Rd		
City	State	Zip
Yoncalla	OR	97499
Latitude	Longitude	
43.61166	123.21681	
Tracking Code	Inspection Date	
RVS in 2006	8/9/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	-0.4	0	0	5.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Douglas County Fire & EMS

Final RVS Score

Final Type	Final Score
W2	5.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

North Douglas County Fire & EMS

Doug_fir43A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
<p>N Plan Irregularity Primary back wall is solid indicating a potential torsion problem.</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries