

# Myrtle Creek Police Dept

City of Myrtle Creek

Doug\_pol02A

Building Type Police - City	County Douglas	
Street 215 NW Pleasant St		
City Myrtle Creek	State OR	Zip 97457
Latitude 43.02675	Longitude 123.2886	
Tracking Code RVS in 2006	Inspection Date 8/25/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	-0.4	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Myrtle Creek Police Dept

## Final RVS Score

Final Type	Final Score
RM1	1.4

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Myrtle Creek Police Dept

Doug\_pol02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		None	
None		None	
None		None	
			
S Other pounding potential (1")		W Vertical Irregularity Primary (both primary and secondary structural system)	
		N Vertical Irregularity Primary	
			
W Vertical Irregularity Secondary		W Falling Hazard parapet	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries