

Roseburg Police Dept

City of Roseburg

Doug_pol03A

Building Type		County	
Police - City		Douglas	
Street			
205 SE Jackson St			
City	State	Zip	
Roseburg	OR	97470	
Latitude		Longitude	
43.21197		123.34148	
Tracking Code		Inspection Date	
RVS in 2006		8/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	W1	4.4	0	0	0	2.4	0	0	0	6.8
Tertiary		0	0	0	0	0	0	0	0	0

Roseburg Police Dept

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E General Site