

Douglas County Sheriff's Office

Douglas County

Doug_pol06A

Building Type		County	
Police - County		Douglas	
Street			
129 W C Ave			
City	State	Zip	
Drain	OR	97435	
Latitude		Longitude	
43.66331		123.31585	
Tracking Code		Inspection Date	
RVS in 2006		8/9/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	URM	1.8	0	0	0	0	-0.4	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Douglas County Sheriff's Office

Final RVS Score

Final Type

Final Score

URM

1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Primary Structural Type

N Pounding Potential
between one story RM1 building.