

Winston Police Department

City of Winston

Doug_pol09A

Building Type		County	
Police-City		Douglas	
Street			
201 NW Douglas St			
City	State	Zip	
Winston	OR	97496	
Latitude		Longitude	
43.12172		123.41596	
Tracking Code		Inspection Date	
RVS in 2006		8/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Secondary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

Winston Police Department

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
291			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Plan Irregularity Primary

NW Plan Irregularity Primary
also shows the RM section on the right and W2 on the left.