

South Umpqua High School

South Umpqua SD 19

Doug_sch17A

Building Type	County	
School	Douglas	
Street		
501 NW Chadwick Ln		
City	State	Zip
Myrtle Creek	OR	97457
Latitude	Longitude	
42.98705	123.32838	
Tracking Code	Inspection Date	
RVS in 2006	8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

South Umpqua High School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Umpqua High School

Doug_sch17A

Enrollment 554	Year Built (Field Verified) 1965	Year Built (Alt. Source) 1965	Est. Decade Built 1970	
Total Area (square ft) 115000	Number of Stories 1	Basement	Pounding Potential No	
Plan Irregularities		Vertical Irregularities		
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes		
Large Diaphragm or Central Opening		None		
None		None		
Falling Hazards		Poor Conditions		
None		None		
None		None		
None		None		
				
N	Vertical Irregularity Primary	N	Primary Structural Type	
			W	Plan Irregularity Primary
				
				
E	Plan Irregularity Secondary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries