

Riddle Elementary School

Riddle SD 70

Doug_sch20A

Building Type School	County Douglas	
Street Fifth & Park Streets		
City Riddle	State OR	Zip 97469
Latitude 42.95428	Longitude 123.36177	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riddle Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Riddle Elementary School

Doug_sch20A

Enrollment 227	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 40000	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Non-Parallel System		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Vertical Irregularity Primary		SE Plan Irregularity Primary	
		E Plan Irregularity Secondary	
		NW Plan Irregularity Tertiary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries