

Glendale Elementary School

Glendale SD 77

Doug_sch22A

Building Type School	County Douglas	
Street 100 Pacific Ave		
City Glendale	State OR	Zip 97442
Latitude 42.73582	Longitude 123.42454	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Glendale Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Glendale Elementary School

Doug_sch22A

Enrollment 241	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 58512	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Large Diaphragm or Central Opening		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Vertical Irregularity Primary	SW	Plan Irregularity Primary
			
		E	Plan Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries