

# Winston Middle School

Winston-Dillard SD 116

Doug\_sch25A

Building Type School	County Douglas	
Street 330 SE Thompson Ave		
City Winston	State OR	Zip 97496
Latitude 43.11461	Longitude 123.40896	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Winston Middle School

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Winston Middle School

Doug\_sch25A

Enrollment 255	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1950	Est. Decade Built
Total Area (square ft) 56534	Number of Stories 1	Basement	Pounding Potential No
<b>Plan Irregularities</b> Reentrant Corners: Other Reentrant Corners: Other (Adjacent Build/Entity) None		<b>Vertical Irregularities</b> Steps in Elevation View: Very Irregular Changes Building On Hill or Sloped Site Steps in Elevation View: Single Change (Adjacent Building/Entity)	
<b>Falling Hazards</b> None None None		<b>Poor Conditions</b> Cracks None None	
			
E Primary Structural Type	SE Plan Irregularity Primary	W Vertical Irregularity Primary	
			
W Vertical Irregularity Secondary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
 Oregon Department of Geology and Mineral Industries

# Winston Middle School

Winston-Dillard SD 116

Doug\_sch25B

Building Type School	County Douglas	
Street 330 SE Thompson Ave		
City Winston	State OR	Zip 97496
Latitude 43.11438	Longitude 123.40944	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Winston Middle School

### Final RVS Score

Final Type	Final Score
C2	0.9

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Winston Middle School

Doug\_sch25B

Enrollment 255	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 56534	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Elevation View		E Vertical Irregularity Primary	
			
		SW Poor Condition	

# Winston Middle School

Winston-Dillard SD 116

Doug\_sch25C

Building Type School	County Douglas	
Street 330 SE Thompson Ave		
City Winston	State OR	Zip 97496
Latitude 43.11418	Longitude 123.40878	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	-0.4	0	0	5.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Winston Middle School

### Final RVS Score

Final Type	Final Score
W2	5.3

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Winston Middle School

Doug\_sch25C

Enrollment 255	Year Built (Field Verified) 1966	Year Built (Alt. Source) 1966	Est. Decade Built 1980
Total Area (square ft) 56534	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	