

Brockway Elementary School

Winston-Dillard SD 116

Doug_sch31A

Building Type	County	
School	Douglas	
Street		
2520 Nw Brockway Rd		
City	State	Zip
Winston	OR	97496
Latitude	Longitude	
43.12473	123.44292	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Brockway Elementary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
367		2003	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions