

Oakland High School

Oakland SD 1

Doug_sch37A

Building Type	County	
School	Douglas	
Street		
521 NE Spruce St		
City	State	Zip
Oakland	OR	97462
Latitude	Longitude	
43.42767	123.29815	
Tracking Code	Inspection Date	
RVS in 2006	8/18/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary	S3	3.2	0	-0.5	0	0	0	0	0	2.7

Oakland High School

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oakland High School

Doug_sch37A

Enrollment 203	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1950
Total Area (square ft) 51202	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements		None	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
NW Falling Hazard and reentrant corner		SW Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oakland High School

Oakland SD 1

Doug_sch37B

Building Type School	County Douglas	
Street 521 NE Spruce St		
City Oakland	State OR	Zip 97462
Latitude 43.42821	Longitude 123.29814	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Oakland High School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Oakland High School

Doug_sch37B

Enrollment 203	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1970
Total Area (square ft) 51202	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Elevation View		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oakland High School

Oakland SD 1

Doug_sch37C

Building Type School	County Douglas	
Street 521 NE Spruce St.		
City Oakland	State OR	Zip 97462
Latitude 43.42813	Longitude 123.29761	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oakland High School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Oakland High School

Doug_sch37C

Enrollment 203	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1950
Total Area (square ft) 51202	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SE Plan Irregularity Primary and step in elevation		NE Elevation View	