

OSP

Gran_pol01A

Oregon State Police

Building Type Police - State	County Grant	
Street 420 W Main St.		
City John Day	State OR	Zip 97845
Latitude 44.41752	Longitude 118.95787	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

OSP

Final RVS Score

Final Type	Final Score
C2	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No
Plan Irregularities		Vertical Irregularities	
None		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Vertical Irregularity Primary			

