

Burns Fire Dept

City of Burns

Harn_fir02A

Building Type		County	
Fire - City		Harney	
Street			
50 W Van Buren St			
City	State	Zip	
Burns	OR	97720	
Latitude		Longitude	
43.58382		119.05493	
Tracking Code		Inspection Date	
RVS in 2006		6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary	W1	5.2	-3.5	-0.5	0	0	0	-0.6	0	0.6
Tertiary		0	0	0	0	0	0	0	0	0

Burns Fire Dept

Final RVS Score

Final Type

Final Score

RM1

-0.5

FEMA-154 Collapse Potential

Very High (100%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1940	1940	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes

Plan Irregularities	Vertical Irregularities
Lateral-Force-Resistance in One Direction Only	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Primary Structural Type
RM1 inside window.

W General Site

