

# Harney County Sheriff Department

Harney County

Harn\_pol02A

Building Type	County
EOC-Public Safety Answering P	Harney
Street	
485 North Court	
City	State Zip
Burns	OR 97720
Latitude	Longitude
43.58968	119.05731
Tracking Code	Inspection Date
New Building	6/29/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3.6	-2	0	0	1.4	-0.8	0	0	2.2
Secondary	S3	3.8	0	0	0	0	-0.6	0	0	3.2
Tertiary	S4	3.6	-2	0	0	1.2	-0.8	0	0	2

Harney County Sheriff Department

## Final RVS Score

Final Type	Final Score
S4	2

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harney County Sheriff Department

Harn\_pol02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1998	1941	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
W	Elevation View	E	Elevation View

# Harney County Sheriff Department

Harney County

Harn\_pol02B

Building Type	County
EOC-Public Safety Answering P	Harney
Street	
845 North Court	
City	State Zip
Burns	OR 97720
Latitude	Longitude
43.5895	119.05733
Tracking Code	Inspection Date
RVS in 2006	6/29/2006



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harney County Sheriff Department

**Final RVS Score**

Final Type	Final Score
C2	0.8

**FEMA-154 Collapse Potential**

High (>10%)
-------------



# Harney County Sheriff Department

Harn\_pol02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1962	1941	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Elevation View		W Elevation View inmate	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries