

Hood River County Sheriff

Hood River County

Hood_pol01A

Building Type	County
EOC-Public Safety Answering P	Hood
Street	
309 State St	
City	State Zip
Hood River	OR 97031
Latitude	Longitude
45.70776	121.51369
Tracking Code	Inspection Date
RVS in 2006	8/2/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	0	0	0	1.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hood River County Sheriff

Final RVS Score

Final Type	Final Score
C2	1.6

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hood River County Sheriff

Hood_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1953	1953	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		None	
Heavy Cladding (thick stone or concrete)		None	
Unreinforced Chimneys		None	
			
N	General Site	W	Elevation View
			
S	Falling Hazard urm smoke stack		
			
S	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hood River County Sheriff

Hood River County

Hood_pol01B

Building Type	County
EOC-Public Safety Answering P	Hood
Street	
309 State St	
City	State Zip
Hood River	OR 97031
Latitude	Longitude
45.70775	121.51341
Tracking Code	Inspection Date
RVS in 2006	8/2/2006



Hood River County Sheriff

Final RVS Score

Final Type	Final Score
C2	1.6

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hood River County Sheriff

Hood_pol01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1953	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	3	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: General		None	
None		None	
None		None	
			
E	General Site	NE	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries