

Parkdale Elementary School

Hood River County SD

Hood_sch01A

Building Type School	County Hood	
Street 4880 Van Nuys Dr		
City Parkdale	State OR	Zip 97041
Latitude 45.52198	Longitude 121.59336	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	-1.2	0	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parkdale Elementary School

Final RVS Score

Final Type	Final Score
C2	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Parkdale Elementary School

Hood_sch01A

Enrollment 267	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 1930
Total Area (square ft) 40311	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Building On Hill or Sloped Site	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Primary Structural Type	S Other	S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parkdale Elementary School

Hood River County SD

Hood_sch01B

Building Type School	County Hood	
Street 4880 Van Nuys Dr		
City Parkdale	State OR	Zip 97041
Latitude 45.52184	Longitude 121.59394	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	W2	4.8	0	-0.5	0	1.6	0	-1.2	0	4.7
Tertiary	PC1	3.2	0	-0.5	0	0	0	-1	0	1.7

Parkdale Elementary School

Final RVS Score

Final Type	Final Score
PC1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Parkdale Elementary School

Hood_sch01B

Enrollment 267	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 1980
Total Area (square ft) 40311	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: L Shaped Reentrant Corners: L Shaped (Adjacent Build/Entity) None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Primary Structural Type		 S Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parkdale Elementary School

Hood River County SD

Hood_sch01C

Building Type	County	
School	Hood	
Street		
4880 Van Nuys Dr		
City	State	Zip
Parkdale	OR	97041
Latitude	Longitude	
45.52203	121.59393	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	2	0	-1.2	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parkdale Elementary School

Final RVS Score

Final Type	Final Score
RM1	3.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parkdale Elementary School

Hood_sch01C

Enrollment 267	Year Built (Field Verified) 1937	Year Built (Alt. Source) 1937	Est. Decade Built 2000
Total Area (square ft) 40311	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Primary Structural Type			