

Wy'East Middle School

Hood River County SD

Hood_sch03A

Building Type	County	
School	Hood	
Street		
3000 Wy'East Rd		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.63785	121.55612	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	-1.6	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wy'East Middle School

Final RVS Score

Final Type	Final Score
C2	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Wy'East Middle School

Hood_sch03A

Enrollment 460	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1950
Total Area (square ft) 84616	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Short Columns	
None		None	
Falling Hazards		Poor Conditions	
Other: Smokestack		None	
None		None	
None		None	
			
S	Elevation View	S	Primary Structural Type
			
S	Elevation View	N	Elevation View
			
N	General Site	E	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood River County SD

Hood_sch03B

Building Type	County	
School	Hood	
Street		
3000 Wy'East Rd		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.63729	121.55616	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	0	0	0	0	0	-1.6	1.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wy'East Middle School

Final RVS Score

Final Type	Final Score
PC1	1.6

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Wy'East Middle School

Hood_sch03B

Enrollment 460	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1970
Total Area (square ft) 84616	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Primary Structural Type		 N Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood River County SD

Hood_sch03C

Building Type	County	
School	Hood	
Street		
3000 Wy'East Rd		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.63734	121.55689	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	0	-1.8	-0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wy'East Middle School

Final RVS Score

Final Type	Final Score
W2	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood_sch03C

Enrollment 460	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1960
Total Area (square ft) 84616	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 N General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood River County SD

Hood_sch03D

Building Type	County	
School	Hood	
Street		
3000 Wy'East Rd		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.63816	121.55644	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3.6	0	0	0	1.4	0	0	-1.6	3.4
Secondary	C2	3.6	0	0	0	1.6	0	0	-1.6	3.6
Tertiary		0	0	0	0	0	0	0	0	0

Wy'East Middle School

Final RVS Score

Final Type	Final Score
S2	3.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood_sch03D

Enrollment 460	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 2000
Total Area (square ft) 84616	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Primary Structural Type	N Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wy'East Middle School

Hood River County SD

Hood_sch03E

Building Type	County	
School	Hood	
Street		
3000 Wy'East Rd		
City	State	Zip
Hood River	OR	97031
Latitude	Longitude	
45.63789	121.55582	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	1.6	0	0	-1.6	3.1
Secondary	S2	3.6	0	-0.5	0	1.4	0	0	-1.6	2.9
Tertiary		0	0	0	0	0	0	0	0	0

Wy'East Middle School

Final RVS Score

Final Type	Final Score
S2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Wy'East Middle School

Hood_sch03E

Enrollment 460	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 2000
Total Area (square ft) 84616	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Torsion: Building Shape None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries