

# Rogue River Rural Fire Dist

Jack\_fir06A

Rogue River RFPD

Building Type	County
Fire - RFPD	Jackson
Street	
5474 N River Rd	
City	State Zip
Gold Hill	OR 97525
Latitude	Longitude
42.42986	123.16109
Tracking Code	Inspection Date
RVS in 2006	7/19/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Rogue River Rural Fire Dist

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Plan Irregularity Primary	S	Plan Irregularity Secondary also shows vertical irregularity
			
N	Secondary Structural Type	E Vertical Irregularity Secondary	

