

Evans Valley Fire District 6

Evans Valley Fire Dist #6

Jack_fir07A

Building Type	County	
Fire - RFPD	Jackson	
Street		
8677 E Evans Creek Rd		
City	State	Zip
Rogue River	OR	97537
Latitude	Longitude	
42.53902	123.15178	
Tracking Code	Inspection Date	
RVS in 2006	7/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Evans Valley Fire District 6

Final RVS Score

Final Type	Final Score
W2	3.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Evans Valley Fire District 6

Jack_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Plan Irregularity Primary	NE	General Site Also shows garage doors are on both sides indicating that there is no torsion problem.



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries