

Applegate Valley RFPD 9

Applegate Valley RFPD

Jack_fir08A

Building Type Fire - RFPD	County Jackson	
Street 18489 N Applegate Rd		
City Grants Pass	State OR	Zip 97527
Latitude 42.25681	Longitude 123.17066	
Tracking Code RVS in 2006	Inspection Date 7/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Tertiary		0	0	0	0	0	0	0	0	0

Applegate Valley RFPD 9

Final RVS Score

Final Type	Final Score
S3	2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Applegate Valley RFPD 9

Jack_fir08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
S Secondary Structural Type reentrant corner			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries