

Medford Fire Dept - City Hall Lausmann Annex

Jack_fir10A

City of Medford

Building Type		County	
Fire - City		Jackson	
Street			
200 S Ivy St			
City	State	Zip	
Medford	OR	97501	
Latitude		Longitude	
42.32253		122.87597	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Medford Fire Dept - City Hall
Lausmann Annex

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Medford Fire Dept - City Hall Lausmann Annex

Jack_fir10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1997	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site



S General Site