

Medford Fire Dept Station 6

City of Medford

Jack_fir24A

Building Type Fire - City	County Jackson	
Street 3700 Barnett Rd		
City Medford	State OR	Zip 97501
Latitude 42.31693	Longitude 122.81215	
Tracking Code New Building	Inspection Date 9/15/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Medford Fire Dept Station 6

Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

Medford Fire Dept Station 6

Jack_fir24A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1999	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries