


# Central Point Police Department

City of Central Point

Jack\_pol09A

Building Type Police - City	County Jackson	
Street 155 S 2nd St		
City Central Point	State OR	Zip 97502
Latitude 42.37363	Longitude 122.91435	
Tracking Code RVS in 2006	Inspection Date 7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Point Police Department

Final RVS Score

Final Type	Final Score
C2	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Central Point Police Department

Jack\_pol09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1980	1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View		NW Other Light 2nd story connection to newer building (city hall).	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries