

Talent Middle School

Phoenix-Talent SD 4

Jack_sch01A

Building Type	County	
School	Jackson	
Street		
102 Christian Ave		
City	State	Zip
Talent	OR	97540
Latitude	Longitude	
42.24015	122.79424	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Talent Middle School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Talent Middle School

Jack_sch01A

Enrollment 639	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 69850	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Large Diaphragm or Central Opening		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
NE Plan Irregularity Primary	NW General Site	W Vertical Irregularity Primary	
			
W Plan Irregularity Primary	E Falling Hazard		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Talent Middle School

Phoenix-Talent SD 4

Jack_sch01B

Building Type	County	
School	Jackson	
Street		
102 Christian Ave		
City	State	Zip
Talent	OR	97540
Latitude	Longitude	
42.23964	122.79363	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Talent Middle School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Talent Middle School

Jack_sch01B

Enrollment 639	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 69850	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
N Vertical Irregularity Primary		NE Elevation View	
		W Plan Irregularity Primary	
			
NE Vertical Irregularity Primary		N General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Talent Middle School

Phoenix-Talent SD 4

Jack_sch01C

Building Type	County	
School	Jackson	
Street		
102 Christian Ave		
City	State	Zip
Talent	OR	97540
Latitude	Longitude	
42.23927	122.79366	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Talent Middle School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Talent Middle School

Jack_sch01C

Enrollment 639	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1960
Total Area (square ft) 69850	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: General None None		Poor Conditions None None None	