

# Phoenix High School

Phoenix-Talent SD 4

Jack\_sch02A

Building Type	County	
School	Jackson	
Street		
745 N Rose St		
City	State	Zip
Phoenix	OR	97535
Latitude	Longitude	
42.27653	122.82431	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Phoenix High School

### Final RVS Score

Final Type	Final Score
RM1	-0.1

### FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Phoenix High School

Jack\_sch02A

Enrollment 848	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1990
Total Area (square ft) 131525	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		Steps in Elevation View: Very Irregular Changes Internal Discontinuous Diaphragm (large internal opening) None	
Falling Hazards		Poor Conditions	
None None None		None None None	
			
NE Plan Irregularity Primary		NE Elevation View	
		E Plan Irregularity Primary	
		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Phoenix High School

Phoenix-Talent SD 4

Jack\_sch02B

Building Type	County
School	Jackson
Street	
745 N Rose St	
City	State Zip
Phoenix	OR 97535
Latitude	Longitude
42.27594	122.82336
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Phoenix High School

Final RVS Score

Final Type

Final Score

RM1

0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Phoenix High School

Jack\_sch02B

Enrollment 848	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1990
Total Area (square ft) 131525	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Elevation View			

# Phoenix High School

Phoenix-Talent SD 4

Jack\_sch02C

Building Type	County	
School	Jackson	
Street		
745 N Rose St		
City	State	Zip
Phoenix	OR	97535
Latitude	Longitude	
42.27567	122.82383	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Phoenix High School

## Final RVS Score

Final Type	Final Score
RM1	0.3

## FEMA-154 Collapse Potential

High (>10%)



# Phoenix High School

Jack\_sch02C

Enrollment 848	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1990
Total Area (square ft) 131525	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
 S Vertical Irregularity Primary		 W Plan Irregularity Primary Also show a vertical irregularity.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Phoenix High School

Phoenix-Talent SD 4

Jack\_sch02D

Building Type	County
School	Jackson
Street	
745 N Rose St	
City	State Zip
Phoenix	OR 97535
Latitude	Longitude
42.277	122.82537
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Phoenix High School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Phoenix High School

Jack\_sch02D

Enrollment 848	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1990
Total Area (square ft) 131525	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	