

# Walker Elementary School

Jack\_sch05A

Ashland SD 5

Building Type		County	
School		Jackson	
Street			
364 Walker Ave			
City	State	Zip	
Ashland	OR	97520	
Latitude		Longitude	
42.18836		122.68758	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Walker Elementary School

## Final RVS Score

Final Type

Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
382		1948	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
43108	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions