

Building Type	County	
School	Jackson	
Street		
100 Walker Ave		
City	State	Zip
Ashland	OR	97520
Latitude	Longitude	
42.19262	122.68724	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	1.6	-0.8	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ashland Middle School

## Final RVS Score

Final Type	Final Score
C2	4.4

## FEMA-154 Collapse Potential

Low (&lt;1%)

No  
Planview  
Available



OregonGeology

# Ashland Middle School

Jack\_sch06A

Enrollment 714	Year Built (Field Verified) 1998	Year Built (Alt. Source) 1998	Est. Decade Built
Total Area (square ft) 176563	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries