

Jewett Elementary School

Central Point SD 6

Jack_sch09A

Building Type	County	
School	Jackson	
Street		
1001 Manzanita St		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.37964	122.90916	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jewett Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jewett Elementary School

Jack_sch09A

Enrollment 483	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 45018	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: U shaped		Steps in Elevation View: 2 to 3 Changes	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
E	Vertical Irregularity Primary	E	General Site
			
W	Plan Irregularity Primary		
			
S	Falling Hazard overhead walkway		



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jewett Elementary School

Central Point SD 6

Jack_sch09B

Building Type	County	
School	Jackson	
Street		
1001 Manzanita St		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.37956	122.90987	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jewett Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Jewett Elementary School

Jack_sch09B

Enrollment 483	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1970
Total Area (square ft) 45018	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Jewett Elementary School

Central Point SD 6

Jack_sch09C

Building Type	County	
School	Jackson	
Street		
1001 Manzanita St		
City	State	Zip
Central Point	OR	97502
Latitude	Longitude	
42.37999	122.90915	
Tracking Code	Inspection Date	
RVS in 2006	7/18/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	C1	3	0	-0.5	0	0	0	-1	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Jewett Elementary School

Final RVS Score

Final Type	Final Score
C1	1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jewett Elementary School

Jack_sch09C

Enrollment 483	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1960
Total Area (square ft) 45018	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Eccentric Stiffness None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries