

# Sams Valley Elementary School

Central Point SD 6

Jack\_sch12A

Building Type		County	
School		Jackson	
Street			
14235 Table Rock Rd			
City	State	Zip	
Central Point	OR	97502	
Latitude		Longitude	
42.49327		122.93574	
Tracking Code		Inspection Date	
RVS in 2006		7/18/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Tertiary		0	0	0	0	0	0	0	0	0

Sams Valley Elementary School

## Final RVS Score

Final Type

Final Score

RM1

2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
264		1966	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40063	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

# Sams Valley Elementary School

Central Point SD 6

Jack\_sch12B

Building Type		County	
School		Jackson	
Street			
14235 Table Rock Rd			
City	State	Zip	
Central Point	OR	97502	
Latitude		Longitude	
42.49396		122.93573	
Tracking Code		Inspection Date	
RVS in 2006		7/18/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Sams Valley Elementary School

## Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
264		1966	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40063	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Vertical Irregularity Primary



# Sams Valley Elementary School

Central Point SD 6

Jack\_sch12C

Building Type		County	
School		Jackson	
Street			
14235 Table Rock Rd			
City	State	Zip	
Central Point	OR	97502	
Latitude		Longitude	
42.49333		122.93628	
Tracking Code		Inspection Date	
RVS in 2006		7/18/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Sams Valley Elementary School

## Final RVS Score

Final Type

Final Score

RM1

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
264		1966	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40063	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: H Shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Plan Irregularity Primary

