

Rogue River Middle School

Rogue River SD 35

Jack_sch21A

Building Type	County	
School	Jackson	
Street		
301 Pine St		
City	State	Zip
Rogue River	OR	97537
Latitude	Longitude	
42.4366	123.17069	
Tracking Code	Inspection Date	
RVS in 2006	7/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rogue River Middle School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rogue River Middle School

Jack_sch21A

Enrollment 289	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 42158	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Plan Irregularity Primary	W	General Site
			
		W	Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries