

Jefferson Elementary School

Medford SD 549C

Jack_sch28A

Building Type	County	
School	Jackson	
Street		
333 Holmes Ave		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.30865	122.86948	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Jefferson Elementary School

Jack_sch28A

Enrollment 543	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1970
Total Area (square ft) 38185	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
E	Plan Irregularity Primary	N	Vertical Irregularity Primary
			
W	Falling Hazard	W	Vertical Irregularity Primary
			
W	Vertical Irregularity Primary	W	Plan Irregularity Secondary Joint to newer building



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jefferson Elementary School

Medford SD 549C

Jack_sch28B

Building Type	County
School	Jackson
Street	
333 Holmes Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.3084	122.86948
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Jefferson Elementary School

Jack_sch28B

Enrollment 543	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1980
Total Area (square ft) 38185	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jefferson Elementary School

Medford SD 549C

Jack_sch28C

Building Type	County	
School	Jackson	
Street		
333 Holmes Ave		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.30866	122.86916	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Jefferson Elementary School

Jack_sch28C

Enrollment 543	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1980
Total Area (square ft) 38185	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Pounding Potential Joint			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jefferson Elementary School

Medford SD 549C

Jack_sch28D

Building Type	County
School	Jackson
Street	
333 Holmes Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.30852	122.86856
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Jefferson Elementary School

Jack_sch28D

Enrollment 543	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1970
Total Area (square ft) 38185	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jefferson Elementary School

Medford SD 549C

Jack_sch28E

Building Type	County
School	Jackson
Street	
333 Holmes Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.30856	122.86824
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jefferson Elementary School

Jack_sch28E

Enrollment 543	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1970
Total Area (square ft) 38185	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	