

Kennedy Elementary School

Medford SD 549C

Jack_sch31A

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35845		122.85178	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

3.5

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Medford SD 549C

Jack_sch31B

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35821		122.85175	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	Vertical Change in Structural Type (Soft over Stiff)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary
also shows reentrant corner.



E Vertical Irregularity Primary
also show out of plane lateral system



Kennedy Elementary School

Medford SD 549C

Jack_sch31C

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35844		122.85117	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Primary Structural Type



Kennedy Elementary School

Jack_sch31D

Medford SD 549C

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35866		122.85092	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary

Kennedy Elementary School

Medford SD 549C

Jack_sch31E

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.3589		122.85094	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	-0.2	0	0	5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W1

5

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Medford SD 549C

Jack_sch31F

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35889		122.85118	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Jack_sch31G

Medford SD 549C

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35912		122.85148	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Medford SD 549C

Jack_sch31H

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35932		122.85179	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View
also shows reentrant corner and elevation step.



Kennedy Elementary School

Jack_sch31I

Medford SD 549C

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.3591		122.85208	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Jack_sch31J

Medford SD 549C

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35888		122.85177	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Kennedy Elementary School

Medford SD 549C

Jack_sch31K

Building Type		County	
School		Jackson	
Street			
2860 N Keene Way Dr			
City	State	Zip	
Medford	OR	97504	
Latitude		Longitude	
42.35866		122.85148	
Tracking Code		Inspection Date	
RVS in 2006		7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Kennedy Elementary School

Final RVS Score

Final Type

Final Score

W2

4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
547		1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
53550	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

