

| | | |
|--------------------|-----------------|-------|
| Building Type | County | |
| School | Jackson | |
| Street | | |
| 3101 McLoughlin Dr | | |
| City | State | Zip |
| Medford | OR | 97504 |
| Latitude | Longitude | |
| 42.3632 | 122.83711 | |
| Tracking Code | Inspection Date | |
| New Building | 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Abraham Lincoln Elementary

Final RVS Score

| Final Type | Final Score |
|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> |

FEMA-154 Collapse Potential

 Low (<1%)

No
Planview
Available



Abraham Lincoln Elementary

Jack_sch37A

| | | | |
|---------------------------------|-------------------------------------|----------------------------------|--------------------------|
| Enrollment 525 | Year Built (Field Verified) 1996 | Year Built (Alt. Source) 1996 | Est. Decade Built |
| Total Area (square ft) 63438 | Number of Stories | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |