


# Culver Police Dept

City of Culver

Jeff\_pol02A

Building Type Police - City	County Jefferson	
Street 200 1st Ave		
City Culver	State OR	Zip 97734
Latitude 44.52706	Longitude 121.20958	
Tracking Code RVS in 2006	Inspection Date 8/9/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Culver Police Dept

## Final RVS Score

Final Type	Final Score
RM1	0.3

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Culver Police Dept

Jeff\_pol02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View		SE Elevation View	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries