

City of Madras

Building Type Police - City	County Jefferson	
Street 71 SE D St		
City Madras	State OR	Zip 97741
Latitude 44.63325	Longitude 121.1281	
Tracking Code RVS in 2006	Inspection Date 8/9/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Madras Police Dept

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Madras Police Dept

Jeff\_pol05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1965	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5818	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries