

# Warm Springs Elementary School

Jefferson County SD 509J

Jeff\_sch01A

Building Type		County	
School		Jefferson	
Street			
1114 Wasco St			
City	State	Zip	
Warm Springs	OR	97761	
Latitude		Longitude	
44.76481		121.27151	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Warm Springs Elementary School

## Final RVS Score

Final Type

Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Warm Springs Elementary School

Jeff\_sch01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1938	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45105	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Elevation View

# Warm Springs Elementary School

Jefferson County SD 509J

Jeff\_sch01B

Building Type		County	
School		Jefferson	
Street			
1114 Wasco St			
City	State	Zip	
Warm Springs	OR	97761	
Latitude		Longitude	
44.76482		121.27188	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Warm Springs Elementary School

## Final RVS Score

Final Type

Final Score

C2

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1938	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45105	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Elevation View





# Warm Springs Elementary School

Jefferson County SD 509J

Jeff\_sch01C

Building Type		County	
School		Jefferson	
Street			
1114 Wasco St			
City	State	Zip	
Warm Springs	OR	97761	
Latitude		Longitude	
44.76451		121.27198	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	1.6	-0.8	0	0	5.1
Secondary	S2	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Warm Springs Elementary School

## Final RVS Score

Final Type

Final Score

S2

2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1938	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45105	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



# Warm Springs Elementary School

Jefferson County SD 509J

Jeff\_sch01D

Building Type		County	
School		Jefferson	
Street			
1114 Wasco St			
City	State	Zip	
Warm Springs	OR	97761	
Latitude		Longitude	
44.76466		121.2707	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	-0.4	0	0	0.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Warm Springs Elementary School

## Final RVS Score

Final Type

Final Score

URM

0.6

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1938	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45105	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: L Shaped	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Plan Irregularity Secondary

