

Redwood - Building U (Gym)

Jose_coc01A

Rogue CC

Building Type	County	
Community_College	Josephine	
Street		
3345 Redwood Hwy		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.41312	123.39305	
Tracking Code	Inspection Date	
Miller 2004-05	7/25/2005	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Redwood - Building U (Gym)


Final RVS Score

Final Type	Final Score
------------	-------------

W2 1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Redwood - Building U (Gym)

Jose_coc01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
12365	1965	1965	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
12365	1	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		Yes: Unknown	
Falling Hazards		Poor Conditions	
None			
None			
None			