

Rogue CC

Jose_coc02A

Building Type		County	
Community_College		Josephine	
Street			
3345 Redwood Hwy			
City		State	Zip
Grants Pass		OR	97527
Latitude		Longitude	
42.4117		123.3918	
Tracking Code		Inspection Date	
Miller 2004-05		7/26/2005	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	-2.4	0	0	0	-1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Redwood - Coats Hall

Final RVS Score

Final Type


Final Score

W2

-1.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1988	1988	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
18673	1	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	None

Falling Hazards	Poor Conditions
None	
None	
None	

