

Redwood - Firehouse Art Ctr./Small Bus. Dev. Ctr

Jose coc04A

Rogue CC

Building Type	County	
Community_College	Josephine	
Street		
214 SW Fourth St		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.43935	123.33024	
Tracking Code	Inspection Date	
Miller 2004-05	7/25/2005	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card


Redwood - Firehouse Art Ctr./Small Bus. Dev. Ctr

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1912	1912	1910
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16000	2	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		Yes: Unknown	
Falling Hazards		Poor Conditions	
Parapets: General			
None			
None			