

Redwood - Café - Redwood

Jose_coc05A

Rogue CC

Building Type Community_College	County Josephine	
Street 3345 Redwood Hwy		
City Grants Pass	State OR	Zip 97527
Latitude 42.41213	Longitude 123.39315	
Tracking Code RVS in 2006	Inspection Date 8/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4		-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Redwood - Café - Redwood

Final RVS Score

Final Type	Final Score
W1	3.9

FEMA-154 Collapse Potential

Low (<1%)



Redwood - Café - Redwood

Jose_coc05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1965	1965	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10292	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Plan Irregularity Primary	E	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries