

Applegate Valley RFPD 9

Applegate Valley RFPD

Jose_fir07A

Building Type Fire - RFPD	County Josephine	
Street 1076 Kubli Rd		
City Grants Pass	State OR	Zip 97527
Latitude 42.31545	Longitude 123.23004	
Tracking Code New Building	Inspection Date 7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Applegate Valley RFPD 9

Final RVS Score

Final Type	Final Score
S3	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Applegate Valley RFPD 9

Jose_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1998	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1512	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	