

Three Rivers Community Hospital - Grants Pass

Jose_hos01A

Asante Health System NFP

Building Type		County	
Hospital		Josephine	
Street			
500 Ramsey Ave			
City	State	Zip	
Grants Pass	OR	97527	
Latitude		Longitude	
42.42138		123.34291	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Three Rivers Community Hospital - Grants Pass

Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Three Rivers Community Hospital - Grants Pass

Jose_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2001	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
193736		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site