

Josephine County Sheriff / Grants Pass Police Dept

Jose_pol01A

Josephine County

Building Type	County	
Police - County	Josephine	
Street		
500 NW 6th St		
City	State	Zip
Grants Pass	OR	97526
Latitude		Longitude
42.44293		123.32574
Tracking Code		Inspection Date
RVS in 2006		7/24/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Josephine County Sheriff / Grants Pass Police Dept

Final RVS Score

Final Type

Final Score

RM2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1976	1976	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: L Shaped	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W General Site



N General Site



N Pounding Potential



N Vertical Irregularity Primary

NW Primary Structural Type
See next image...NW Primary Structural Type
The masonry can be seen through this hole.

S Plan Irregularity Secondary



S Plan Irregularity Primary

N Primary Structural Type
Inside of stairs