

# Redwood Elementary School

Grants Pass SD 7

Jose\_sch03A

Building Type	County	
School	Josephine	
Street		
3163 Leonard Rd		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.42876	123.39011	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Tertiary		0	0	0	0	0	0	0	0	0

Redwood Elementary School

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Redwood Elementary School

Jose\_sch03A

Enrollment 475	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1980
Total Area (square ft) 47376	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Large Diaphragm or Central Opening		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE General Site	S Vertical Irregularity Primary	S Plan Irregularity Primary	
			
W Secondary Structural Type	N Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries