

# Riverside Elementary School

Jose\_sch04A

Grants Pass SD 7

Building Type		County	
School		Josephine	
Street			
1200 SE Harvey Dr			
City	State	Zip	
Grants Pass	OR	97526	
Latitude		Longitude	
42.42764		123.29879	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverside Elementary School

## Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
401		1961	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
47376	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: U shaped	Steps in Elevation View: 2 to 3 Changes
Out of Plane Lateral-Force-Resistance Elements	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Vertical Irregularity Primary



E Plan Irregularity Secondary

# Riverside Elementary School

Jose\_sch04B

Grants Pass SD 7

Building Type		County	
School		Josephine	
Street			
1200 SE Harvey Dr			
City	State	Zip	
Grants Pass	OR	97526	
Latitude		Longitude	
42.42765		123.29946	
Tracking Code		Inspection Date	
RVS in 2006		7/19/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverside Elementary School

## Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
401		1961	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
131240	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

